Item Ref. No.: 6628 - 10375

To:

The South Australian Heritage Committee

From:

The Senior Historic Architect

Subject:

REGISTER NOMINATION:

- TORTOLA HOUSE, CORNER OF TOD AND DUNDAS STREET, GAWLER

(Also known as the Uniting Church Manse)

Date:

25 January, 1982

SUMMARY

This report is prepared as part of the Register Sub-Committee's programme of evaluating items listed on the Register of the National Estate.

Historically, "Tortola" is significant for its association with two prominent Gawler industrialists and (from 1912) its use as a manse by the Methodist (now Uniting) Church.

Architecturally, the building is a pleasant two storey asymmetric brick building with cloistered balcony and verandah. The diaper brickwork to the front facade is rare and well executed - it is certainly an early and rare example of polychrome and diaper brickwork which to my knowledge is rivalled only by Parkside's former 'Z' Ward.

<u>Environmentally</u>, "Tortola" is an important element with a historical and architectural precinct. Visually, it is an important landmark.

The Integrity of the building is good with only minor structural alterations having been made. "Tortola" is in good structural condition.

"Tortola" is included on the Register of the National Estate and on the Classified List of the National Trust of South Australia.

RECOMMENDATION

It is recommended that Tortola House and its front fence be included on the Register of State Heritage Items, and that it be categorised A1, A2, A3, H2, H3, 3.1.

Barry G. Rowney

SENIOR HISTORIC ARCHITECT

MAB:BAH

25.1.82

South	Register of State Heritage Items				
Australian Heritage	ITEM EVALUATION SHEET Buildings and Structures				
Act 1978-80	Item TORTOLA HOUSE AND FRONT FENCE, CORNER OF TOD AND DUNDAS STREET, GAWLER.				
Component	Comment	Grading E VG AG FP N			
8. Representation	A unique building. An excellent and extremely rare example of "front facadism".	*			
9. Continuity:	Important element which maintains the dominant character of the area.		*		
10. Local Characte	r: Important in establishing and maintaining the dominant character of the area.	*			
11. Landmark:	An important visual and historical landmark.	*			
Integrity					
12. Alterations:	Externally, the lookout platform and railing have been removed. Internally, minor alterations only - former dining room has been partitioned off.	;	*		
13. Condition:	Building is in reasonable condition. Some cracking and fretting of brickwork has occurred.	,	*		
14. Compatibility:	Currently used as a manse by the Uniting Church.	5	*		
Supplementary Info	rmation		11		
15. Adaptation:	Well suited for restoration. High potential for adaptation.				
16. Interpretation	: High potential for interpretation as part of broader Gawler programme.				
17. Current Situat	ion: No known threat.				
	Annely Aeuckens fuges Register Historian	Date			
Reviewed By Mark Actir			Z.8		
		Date	discourant and the same		

