South Australian Heritage	Register of State Heritage Items ITEM EVALUATION SHEET Buildings and Structures	Australia: Australia: Buil
Act 1978-80	Item MILL, CURRENCY CREEK	1978-86
Age 1855-Unconfirme	Theme d	0ffice 6626-10351
Period 1852–1883	Subject	Region
	SECONDARY INDUSTRY - PROCESSIN PRIMARY P	G OF Murray RODUCTS Riverlands
Building Type MILL	Style EARLY VICTORIAN/UTILITARIAN	Status N.E.R. N.Tr. (C.L.)
Qualitative Data Component History	Comment	Grading E VG AG FP
1. Context:	Represents mid Nineteenth Confarming technology which uthand steam power and provides with the earlier settlers in district, having been built 1855-1864.	ilised wind so a link nother
2. Person/Gro	p: The owner, Daniel Meyrick,	1855-1864. *
3. Event:	Not applicable.	
Architecture		
4. Architect/	Builder: Not readily available.	
5. Design:	- Tower, circular tower we sides, three storeys tall three windows with timber elevated door with access external timber platform door at ground level.	er lintels,
iated building		stone walls,
6. Construction	n: Both buildings of random corrugated iron door on corrugated iron addition	building,
7. Interior:	Painted stone walls, time exposed roof structure.	ber floor, * *
8. Representat	ion: Scarce example of circul	1 1 11 1
Environment	function. No active interpret	
9. Continuity:	Flat open paddocks, nota of vegetation, lake in b	
Date	considerable distance fr	
10. Local Chara	cter: Rural setting, refer to	above. *
ll. Landmark:	Vertical tower contrasts landscape in colour and familiar local landmark, from a great distance.	form

1.E.S./D3/211081

SOUTH kegister of State Heritage Items Australian ITEM EVALUATION SHEET Heritage Buildings and Structures Act Item MILL, CURRENCY CREEK 1978-80 Component Comment Grading Integrity E VG AG FP NA 12. Alterations: Form intact, machinery removed, top of tower removed, internal floors replaced, timber window wall in one end of gable of associated building, remains of an addition to associated building on west side, new roof. 13. Condition: No major defects. 14. Compatability: Vacant at present. Supplementary Information 15. Adaptation: The form of the Tower and associated building should be retained along with their relative isolation on the landscape. Internal adaptation should be permitted. Additional external additions should be minimal and in modern materials with no alterations to structural walls. With the building's continued adaptation in the past 16. Interpretation: and the lack of any tangible remains of its workings the interpretative role of the Mill is largely passive as a reminder on the landscape of a past function. No active interpretation is envisaged. 17. Current Situation: Refer to cover sheet. Evaluated By Date Ivar Nelsen Iris Iwanicki Reviewed By Date Ivar Nelsen South Australian Heritage Committee Categorization Date

HISTORICAL REPORT: FORMER MILL, CURRENCY CREEK

The mill stands on property near Currency Creek which according to the South Australian Gazetteer in 1867, was a postal township in a chiefly agricultural district with hotel, post office and saw mill, the last being the subject of this report. Today, Currency Creek is little change

The Round Mill, situated on the property of Mr. T.C. Maul in Pt. Section 2061, Hundred of Nangkita, was originally built for Daniel Meyrick who owned the property between 1855-1864. Although it was originally intended to be a windmill, the superstructure was never completed and it is thought that steam power was used instead. Other uses over the years have included saw milling, referred to in the Gazetteer in 1866, and according to local stories, as a sly grog store.

In a local context, the Mill represents a past landowner's efforts to raise water from a 90 foot well, as water in the nearby lake was saline. Built of stone, its distinctive shape and isolation make it a notable landmark in the surrounding countryside. Other examples of windmills are related to flour milling unlike the incomplete mill at Currency Creek An earlier example of an operational windmill is found at Mount Barker and was constructed in 1841 by F.R. Nixon. It also was constructed of local stone and timber and operated until the early 1890's.

SOURCES:

Lindsey Harrison: Flour Mills in South Australia
Cyclopaedia of South Australia
South Australian Archives Research Note 58

<u>Iris Iwanicki</u> REGISTER HISTORIAN

22.3.82 II:BAH



PHOTO PROM SLIDE

MILL-CURRENCY CROSK 6626-10351

MAY 30





PHOTO FROM SCIDES


MILL- CURRENCY CREEK 6626-10351

MAY 80



FILM

CURRENCY CREEK HOME OF MR AND MRS PETER KEMP—
GOOLWA NATIONAL PHOTO C.1880)
TRUST MUSEUM
9-10-80



FILM 206 No 4

"HIGGINS BROOK, CURRENCY CREEK, BUILT 1841" BY PRESCOTT SINCLAIR. (UNDATED ORIGINAL WATERCOLOUR PAINTING)

FACSIMILES AND PRINTS ON DISPLAY AT GOOLWA NATIONAL TRUST MUSEUM 9-10-80